



Family: Plymouth | Item No. 4259 OB



**Drawing 1 - Fixture Assembly**



▼ start here

**1**

1. Find a clear area in which you can work.
2. Unpack fixture and glass from carton.
3. Carefully review instructions prior to assembly.

**\*\*\* The construction of this fixture will be accomplished by first assembling the main body of the fixture, making all necessary electrical connections and hanging the fixture from the ceiling.**

**SAFETY WARNING: READ WIRING AND GROUNDING INSTRUCTIONS (I.S. 18) AND ANY ADDITIONAL DIRECTIONS. TURN POWER SUPPLY OFF DURING INSTALLATION. IF NEW WIRING IS REQUIRED, CONSULT A QUALIFIED ELECTRICIAN OR LOCAL AUTHORITIES FOR CODE REQUIREMENTS.**

**2**

1. To assemble fixture, thread center column (1) onto threaded stem (2) - see **Drawing 1**.
2. Thread top stem (3) into top of center column (1).
3. Take top spider assembly (4) and spread out arms (A) until they are equally spaced apart.
4. Slip hole (B) in end of arms (A) over studs (C) on the top of cage assembly (D). Making sure center column stem (3) passes through center hole (E) of spider assembly (4).
5. Attach spider assembly (4) to cage assembly (D) with ball knobs (5) provided.
6. Thread loop (6) onto end of top center stem (3) and tighten.
7. Slip candle sleeve (7) over socket (F).
8. Thread bottom cover (8) onto base of cage assembly (D).
9. Please refer to the hanging instruction sheet (I.S. 19) provided to hang fixture.

Note: Maximum wattage for 4259 fixture is 60 watts per bulb.

12.01.08